

SHELTER[®]

September 2001 • The Magazine for Jobbers & Dealers of Building Products

Acrylic Block Windows

The majority of the acrylic block windows sold in the United States today have well known performance problems, causing them to crack and fail under some of the most common environmental and conventional stress (i.e. altitude pressures, rapid temperature changes, standard cleaning chemicals and unforeseen impacts). Although these recognized acrylic block windows are an

improvement from heavy, poorly insulated and inconvenient glass block windows, their acrylic may lack common impact modifiers and recent technical innovations that are known to enhance the performance of acrylic.

Over the last several years, Crystal View™ acrylic block windows by **Builders Accessories** have been exposed to practical testing in every climate and altitude throughout the United States. With a phenomenal rating of zero product failures, the Crystal View™ acrylic block window has eliminated the problems associated with glass and acrylic blocks, establishing itself as the problem-free block window.



Circle Reader Info No. 219